



2020-2021

Technical Skills Assessment

Agriculture Welding

Results by Standard

Legend (%)		
0-50%	51-75%	76-100%

Assessment: Agriculture Welding	% Correct	% Correct	% Correct
Number tested: 277 *May contain results from Trades and Industry Welding	17-18*	18-19	20-21*
CONTENT STANDARD 1.0: IDENTIFY LAB ORGANIZATION AND SAFETY PROCEDURES	78.75%	77.02%	77.71%
Performance Standard 1.1: Demonstrate general lab safety rules and procedures	78.71%	77.35%	78.45%
1.1.1 Describe general shop safety rules and procedures (i.e., safety test)	97.89%	96.15%	94.67%
1.1.2 Describe OSHA in workplace safety	84.94%	84.13%	84.26%
1.1.3 Comply with the required use of safety glasses, ear protection, gloves, and shoes during lab/shop activities, i.e., personal protection equipment (PPE)	94.13%	89.66%	92.86%
1.1.4 Operate lab equipment according to safety guidelines	73.95%	72.12%	69.73%
1.1.5 Identify and use proper lifting procedures and proper use of support equipment (i.e., rigging, chains, straps, cables)	88.25%	86.06%	88.86%
1.1.6 Utilize proper ventilation procedures for working within the lab/shop area	94.28%	92.31%	89.47%
1.1.7 Identify marked safety areas	84.64%	82.69%	82.08%
1.1.8 Identify the location and the types of fire extinguishers and other fire safety equipment; demonstrate knowledge of the procedures for using fire extinguishers and other fire safety equipment	73.49%	75.00%	74.21%
1.1.9 Identify the location and use of eye wash stations	91.11%	89.66%	91.16%
1.1.10 Identify the location of the posted evacuation routes	84.94%	75.96%	78.45%
1.1.11 Identify and wear appropriate clothing for lab/shop activities	48.49%	45.67%	57.87%
1.1.12 Secure hair and jewelry for lab/shop activities	90.06%	92.31%	90.80%
1.1.13 Demonstrate knowledge of the safety aspects of high voltage circuits	85.54%	86.54%	85.59%
1.1.17 Follow written instructions to complete work assignments	73.19%	65.87%	72.88%
1.1.18 Identify requirements for Hot Work Permits	36.45%	39.66%	43.70%
1.1.19 Identify what constitutes a confined space	58.89%	56.97%	58.35%
Performance Standard 1.2: Identify and utilize proper tools	79.82%	77.88%	76.88%
1.2.1 Identify hand tools and their appropriate usage	97.89%	91.83%	93.22%
1.2.3 Demonstrate safe handling and use of appropriate tools	61.75%	63.94%	60.53%

Assessment: Agriculture Welding	% Correct 17-18*	% Correct 18-19	% Correct 20-21*
Number tested: 277 *May contain results from Trades and Industry Welding			
Performance Standard 1.3: Identify and utilize power tools and equipment	78.41%	73.56%	71.83%
1.3.1 Identify power tools and equipment, and their appropriate usage	93.37%	94.23%	87.41%
1.3.2 Demonstrate safe handling and use of appropriate power tools and equipment	70.93%	63.22%	64.04%
CONTENT STANDARD 2.0: APPLY FUNDAMENTAL PRINT READING, MEASUREMENT AND LAYOUT/FIT-UP TECHNIQUES	63.60%	61.46%	66.02%
Performance Standard 2.1: Demonstrate print reading and sketching practices	61.60%	60.46%	65.56%
2.1.2 Identify and explain industry standard welding symbols	57.53%	56.73%	63.44%
2.1.7 Fabricate parts from a drawing or sketch	65.66%	64.18%	67.68%
Performance Standard 2.3: Utilize layout principles and practices	67.62%	63.46%	66.95%
2.3.3 Select appropriate materials to complete work assignment	60.84%	53.37%	63.92%
2.3.5 Layout parts using measurement practices	74.40%	73.56%	69.98%
CONTENT STANDARD 3.0: IDENTIFY PROPERTIES OF METALS	64.91%	62.14%	64.53%
Performance Standard 3.1: Identify material properties and science	64.91%	62.14%	64.53%
3.1.1 Identify the difference between ferrous and non-ferrous metals	64.91%	62.14%	64.53%
CONTENT STANDARD 4.0: APPLY SHIELDED METAL ARC WELDING (SMAW) TECHNIQUES	70.68%	65.38%	68.52%
Performance Standard 4.1: Safety procedures	61.14%	57.45%	58.60%
4.1.1 Identify and explain different types of welding current and polarity	61.14%	57.45%	58.60%
Performance Standard 4.2: Produce welds using SMAW on carbon steel	89.76%	81.25%	88.38%
4.2.2 Operate SMAW equipment	89.76%	81.25%	88.38%
CONTENT STANDARD 5.0: APPLY GAS METAL ARC WELDING (GMAW-S, GMAW) TECHNIQUES	61.92%	60.03%	61.67%
Performance Standard 5.1: Utilize safety procedures	65.81%	69.23%	65.86%
5.1.4 Demonstrate safe startup, shutdown, disassembly, and cylinder exchange procedures of GMAW equipment	65.81%	69.23%	65.86%
Performance Standard 5.2: Produce welds using GMAW-S on carbon steel	61.27%	58.49%	60.98%
5.2.1 Set up for GMAW-S operations	52.11%	44.71%	55.93%
5.2.2 Operate GMAW-S equipment	62.45%	64.74%	62.63%
5.2.3 Perform welds in the 1F position	61.45%	58.89%	60.77%
5.2.4 Perform welds in the 2F position	65.06%	61.78%	61.38%
5.2.7 Perform welds in the 1G position	62.95%	69.71%	65.38%
5.2.8 Perform welds in the 2G position	56.48%	44.95%	59.20%
5.2.9 Perform welds in the 3G position	66.87%	62.02%	59.81%
CONTENT STANDARD 6.0: APPLY FLUX CORED ARC WELDING (FCAW-G) TECHNIQUE	66.06%	62.98%	64.25%
Performance Standard 6.2: Produce welds using FCAW-G on carbon steel	66.06%	62.98%	64.25%
6.2.1 Set up for FCAW-G operations	78.01%	72.12%	73.85%
6.2.2 Operate FCAW-G equipment	32.83%	32.21%	34.62%

Assessment: Agriculture Welding	% Correct 17-18*	% Correct 18-19	% Correct 20-21*
Number tested: 277 *May contain results from Trades and Industry Welding			
6.2.9 Perform welds in the 3G position	87.35%	84.62%	84.26%
CONTENT STANDARD 7.0: APPLY GAS TUNGSTEN ARC WELDING (GTAW) TECHNIQUES	37.65%	37.98%	41.65%
Performance Standard 7.2: Produce welds using GTAW on carbon steel	37.65%	37.98%	41.65%
7.2.2 Operate GTAW equipment	37.65%	37.98%	41.65%
CONTENT STANDARD 8.0: APPLY THERMAL CUTTING PROCESSES	57.72%	55.51%	60.80%
Performance Standard 8.1: Demonstrate oxy-fuel gas cutting (OFC)	63.96%	61.43%	66.32%
8.1.1 Perform safety inspections of OFC equipment and accessories	49.80%	46.79%	54.72%
8.1.3 Demonstrate safe startup, shutdown, disassembly, and cylinder exchange procedures of OFC equipment	66.97%	65.38%	68.93%
8.1.5 Operate OFC equipment	81.33%	83.41%	84.75%
8.1.6 Perform straight, square edge cutting operations in the flat position	62.65%	49.52%	56.42%
Performance Standard 8.2: Demonstrate plasma arc cutting (PAC) on carbon steel and aluminum	29.67%	28.85%	35.96%
8.2.5 Set up for PAC operations	46.39%	46.15%	49.64%
8.2.6 Operate PAC equipment	12.95%	11.54%	22.28%
CONTENT STANDARD 9.0: IDENTIFY WELDING CODES, INSPECTIONS, AND TESTING PRINCIPLES	59.68%	55.56%	59.74%
Performance Standard 9.1: Identify welding codes, qualifications and certifications	59.74%	56.81%	58.72%
9.1.3 Explain the importance of quality workmanship	70.48%	68.11%	71.83%
9.1.5 Perform a visual inspection of fillet welds	49.00%	45.51%	45.60%
Performance Standard 9.2: Demonstrate welding inspection and testing principles	59.34%	48.08%	65.86%
9.2.3 Examine tack, root passes, intermediate layers, and completed welds	59.34%	48.08%	65.86%
CONTENT STANDARD 10.0: APPLY FABRICATION FUNDAMENTALS	64.05%	63.15%	64.35%
Performance Standard 10.1: Utilize base metal preparation fundamentals	66.15%	63.22%	68.77%
10.1.1 Clean base metal for welding or cutting	57.38%	59.62%	63.08%
10.1.2 Identify and explain joint design	89.16%	87.02%	87.29%
10.1.3 Select the proper joint design based on a welding procedure specification (WPS) or instructor's direction	18.37%	13.94%	36.08%
10.1.4 Mechanically bevel the edge of a mild steel plate (i.e., hand beveller, grinder)	72.59%	66.19%	71.11%
Performance Standard 10.2: Demonstrate fabrication techniques	62.65%	63.10%	61.40%
10.2.1 Demonstrate proper setup of fabrication area, equipment, and materials	76.61%	76.60%	78.05%
10.2.2 Construct projects in the proper sequence	74.10%	74.68%	67.47%
10.2.3 Properly layout projects from welding prints	53.82%	54.49%	54.48%
10.2.4 Check work for accuracy	46.08%	46.63%	45.60%